

Who Reads Instructions Anyway?

The Case of the Failing Floor Coating

By Rick A. Huntley, Senior Coatings Consultant, KTA-Tator, Inc.

Richard Burgess, KTA-Tator, Inc., Series Editor

Several years ago, an upgrade was slated for the warehouse of a distribution facility. Part of the upgrade included recoating the concrete floor. The specification for the project required the concrete floor to be abrasive blast cleaned or scarified to remove laitance and surface contaminants. Additionally, before applying the coatings, the surface was to be tested to ensure it was free of moisture. The testing followed the plastic sheet method as described in ASTM D 4263, Standard Test Method for Indicating Moisture in Concrete by the Plastic Sheet Method.

The specification called for a three-coat system: an epoxy primer applied at 150 to 200 sq ft per gallon, a base coat of 100% solids epoxy applied at a thickness of 20 to 30 mils, and a two-component epoxy topcoat applied at a thickness of 20 to 30 mils.

The painting subcontractor submitted an alternate coating system from a different manufacturer as a substitute to the specified system. The alternate system, which was approved and eventually chosen for application to the floor, consisted of a coat of epoxy primer applied at a recommended dry film thickness (dft) of 3–5 mils, a modified polyamine epoxy intermediate coat applied at a recommended dft of 6–12 mils, and a topcoat of a two-component aliphatic polyester polyurethane applied at a recommended dft of 2–3 mils.

During application of the topcoat, the painting subcontractor experienced problems with its adhesion to the intermediate coat. Within weeks after the application was completed, problems also arose with the adhesion of the topcoat, and scratches appeared in the floor coating. The owner of the facility

were also areas where it appeared that the wheels of a forklift had spun on top of the floor, and, in some cases, had left a black mark on the surface of the floor coating. In other cases, the wheels appeared to remove the top layer of the coating, uncovering a gray intermediate coat. The degree of marring on the floor

varied; the damage was minimal in some of the areas where the coating had been newly applied, while in other areas, the marring was quite extensive.

The floor was also relatively dirty at the time of the inspection. During the inspection, a floor cleaner was used on one area. The floor cleaner removed most of the dirt, but a moderate degree of scratching was still visible.

The topcoat was delaminated in many areas. Although both the topcoat and the

intermediate coat were gray, the delamination was clearly visible because the topcoat was generally dirty and therefore darker than the intermediate coat. The delamination generally occurred in small patches.

The floor coating was closely examined in many areas. The degree of hardness of the topcoat varied considerably. According to the product data sheet for the topcoat, the coating was an “extremely hard, chemical-resistant polyurethane floor coating.” During the site investigation, it was found that an impression could be made in the topcoat with a fingernail. In at least one spot, the



Fig 1: Most scratches on warehouse floor were parallel to length of aisle. Photos courtesy of the author

requested an independent evaluation of the floor coating problems.

The Site Investigation

A visit was made to the distribution facility to examine the floor.

The floor had been coated with a gray-colored coating material. In various areas, there was also yellow striping on the gray floor. The floor was scratched and marred to various degrees throughout most of the facility. Most of the scratches were aligned in the direction of the forklift traffic flow (Fig. 1). For example, most of the scratches in any particular aisle were parallel to the length of the aisle. There

SAND BLAST WITHOUT SAND



The POWER of the AURAND "Tough Guy" allows you to reduce the mess, set-up and clean-up time associated with abrasive blasting. Patented design allows exact depth adjustment for increased cutler life and precision removal. Where dust is a problem, vacuum attachments are available on selected models.

The "Tough Guy" is available at many tool rental outlets. "TEST DRIVE" the different AURAND tools to find the one that is right for your job!

FOR THE NAME OF A RENTAL
OUTLET NEAR YOU
CALL TOLL FREE: 800-860-2872
Since 1937

AURAND

1210 Fls Street
Cincinnati, Ohio 45223-1843
TEL: (513) 541-7200
FAX: (513) 541-3066
Website: www.aurand.net

Cases from the F-Files

topcoat was slightly tacky and could be removed easily with a fingernail and rolled into small balls. In most of the areas examined, the topcoat could be removed from an intermediate coat by scratching the surface with a fingernail. In a few areas, the coating was harder, and could not be removed with fingernail gouging.

The adhesion of the coating system was assessed in accordance with ASTM D3359, "Measuring Adhesion by Tape Test," Method A (X-cut). This method involves making two intersecting cuts through the coating to the substrate with a sharp blade. The smaller angle of the cuts is between 30 and 45 degrees. A special pressure-sensitive tape is then applied to the X-cut area and rapidly removed.

In many of the areas tested, the coating adhesion was extremely poor (Fig. 2). In some cases, the coating could be removed simply by applying the tape to the uncut topcoat and sharply pulling off the tape. In some other areas, the coating adhesion was rated good (4A), yet the topcoat could be removed by scratching at the surface with a finger-



Fig 2: ASTM Tape Test revealed poor coating adhesion

nail. In a few areas, the tape adhesion was found to be good and the topcoat could not be removed with fingernail pressure.

In areas where delamination was observed, the topcoat could be removed easily by cutting the surface with a utility knife and slipping the blade of the utility knife under the topcoat. In some cases, by continuing to tug at the coating, large sections could be removed in one piece (Fig. 3).

During the site visit, several coating samples were removed from the floor for laboratory analysis.

The Laboratory Investigation

Visual and microscopic examination of the samples was performed using a stereo zoom microscope with magnification to 45x. The investigation revealed

that the samples generally consisted of four coats. The first coat was clear and the backside was dirty. There were three off-white coats applied to the clear coating. The topcoat could be removed from the other three coats in areas on some of the chips.



Fig 3: Large sections of coating delaminated with minimal manipulation.

Infrared spectro-

F-Files

scopic analysis was performed with a Fourier transform infrared spectrometer. Sample scrapings were combined with potassium bromide powder and formed into pellets under high pressure. The pellets were then placed in the optical path of the spectrometer and spectra were obtained.

The infrared analysis indicated that the top two coats that were applied to the floor were the urethane topcoat. The primer and the first intermediate coat were determined to be epoxy coatings.

The analysis also revealed that the softer topcoat samples had slightly different spectra than the harder samples of topcoat and a control sample of a properly mixed topcoat. Specifically, one of the bands in the spectra of the soft topcoats was significantly smaller than the same band in the spectra of harder topcoat.

Putting It All Together

The site investigation and the laboratory analysis indicated that the cause of the excessive marring and scratching and of the scattered delamination of the topcoat from the floor in the distribution facility was improper mixing of the urethane topcoat. The topcoat was described as an "extremely hard chemical resistant polyurethane floor coating" in the product data sheet. As noted above, the topcoat on the floor was soft enough in many areas to deform with fingernail pressure. In some other areas, the coating was relatively hard and well adhered.

Laboratory microscopic analysis indicated that there were two layers of topcoat on the samples. When the coating had poor adhesion or had delaminated, it was found that the plane of separation was sometimes between the first layer of topcoat and the epoxy intermediate coat, and sometimes between the two layers of topcoat. The topcoat that separated from the rest of the coating system was found to be soft, regardless of whether it was the first layer or the

Continued

HUNTSMAN
Enriching lives through innovation

Waterborne Products for Epoxy Systems

Aradur® 3986 Curing Agent for Anticorrosive Primer
Aradur® 3805 Curing Agent for Concrete Coating
Araldite® PZ 3921 High Performance Epoxy Emulsion

Copyright © 2009 Huntsman Advanced Materials Americas Inc.

www.huntsman.com/advanced_materials • 888-564-9318
10003 Woodloch Forest Drive, The Woodlands, TX 77380

Click our Reader e-Card at paintsquare.com/r/c

Cement or Epoxy ? MIX ... PUMP ... SPRAY ...

Quikspray, inc. has the best tool for your application !!

Carrousel Pump with U-Blend Mixer
mixes & pumps most commercial coatings

U-Blend Mixer
industrial mixer for all commercial coatings

AG-Blower
place quartz & sand on epoxy floors

Box 327 - Port Clinton, OH 43452 419-732-2611 fax 419-734-2628

Click our Reader e-Card at paintsquare.com/r/c

Cases from the F-Files

second layer of polyurethane topcoat.

The topcoat applied to the warehouse floor is a two-component coating. Polyol in the second component reacts with the isocyanate in the first component to form a hard film. The two components must be mixed thoroughly and in their proper proportion for the coating to obtain its proper hardness. The labora-

tory infrared analysis provided strong evidence that the coatings were not consistently mixed in the proper proportions.

When several samples of a properly mixed two-component coating are compared using infrared spectroscopic analysis, there is usually very little difference between the spectra. In this

case, the difference was very noticeable. The mix ratio of the coating varied considerably from location to location.

The softer coatings were found to adhere poorly to the underlying harder coatings. In some cases, the underlying coating was the epoxy intermediate coat. In other cases, it was an underlying second layer of the polyurethane topcoat. In all cases, the poorly adhered layer was soft.

Some degree of scratching and marling will occur with any organic floor coating exposed to forklift traffic. The degree of damage to the floor was significantly greater than should be expected for the coating system applied. The excess damage was a result of the softness of the applied topcoat. A floor coating that is soft enough to be scratched with a fingernail cannot be expected to withstand forklift traffic. If the coating had been properly mixed, it is likely the damage would have been significantly reduced and adhesion much improved.

The Fix

In a vast majority of the facility, the primer and the epoxy intermediate coat appeared to be in satisfactory condition. Unfortunately, the topcoat could not be overcoated without great risk of further failure. As a result, all of the topcoat had to be removed. Removal was accomplished using pressurized water and in some areas, a scarifying machine. In areas where the topcoat was removed by pressure washing, the uncovered intermediate coat was thoroughly abraded to break the gloss and roughen the surface. A properly mixed coat of the polyurethane was then applied to the prepared intermediate coat. The contractor had to perform the work—which also included temporary relocation of equipment and storage racks—at no cost to the owner. Additional work caused by improperly mixing the topcoat added more than 50% to the total cost of the job.



when the going gets tough...
we get tougher.

Foot traffic, vehicle traffic, heat, cold, the relentless effects of weather... With these kinds of forces stacked against you, it's essential to have a coating that can rise to the challenge - one that you can have confidence in to remain strong and effective no matter how hard you use or abuse it.

Wearcoat® floor coatings define durability. Easy to apply, easy to clean, non-slip and incredibly tough, Wearcoat® will give you the edge you need to get the job done - safely and efficiently. Call us today or check us out on the web. Our expert staff is ready to help with any coating needs you have...

 **COATINGS FOR INDUSTRY, INC.**
Call us today – 215-723-0919 Fax 215-723-0911
www.coatingsforindustry.com

Serving the concrete flooring, structural steel,
transportation and aerospace industries for over 35 years.

OUTSMARTING Murphy's Law

MONDAY 8:00 AM
Begin coating

MONDAY 4:00 PM
Finish coating

MONDAY 11:00 PM
Sprinkler system fails

MONDAY 11:01 PM
Outsmarting Murphy's Law

IT NEVER FAILS: When you count on things going right, they invariably go wrong. That's why Sherwin-Williams offers ExpressTech™ coatings. ExpressTech coatings speed cure times, reducing the risk that unexpected problems will ruin your great coating job. They provide great coverage, too. That means fewer coats, reduced labor costs, improved productivity and faster return to service. Ideal for bridges, tanks, power generation, industrial floors, steel fabrication and other demanding applications. And, a great way to outsmart Murphy's Law. To learn more, contact your Sherwin-Williams representative, visit us at www.sherwin-williams.com/protective or call +1 800.524.5979 to have a representative contact you.



**SHERWIN
WILLIAMS®**

Techno Coatings, Inc.

Field Services



**PAINTING - WATERPROOFING - SANDBLASTING
COVERING BOTH FIELD AND SHOP SERVICES**

SSPC QP Certified
QP1 - QP2 - QP3

Serving Our Customers Since 1974

www.technocoatings.com



Restoration



Commercial



Power Generation



Industrial

**714-635-1130
800-286-1130**



Amusement



Tanks/Abatement



High Work



Stadiums/Arenas



Casinos/Hotels

- Abrasive Blasting - Recyclable Media
- High Build & Specialty Coatings
- Steam & Chemical Cleaning
- High-pressure Hydroblasting
- Epoxy Injection ■ Wall Coverings
- Lead Abatement ■ Fireproofing
- Renovation and Restoration



Offshore

SSPC QP Certified

1391 Allec St. Anaheim, Ca 92805

TECHNO WEST Shop Blasting & Coating

One of the largest Shop Coating facilities in the West



- Automated & Manual Blasting
- Piping, Structural Steel
- Ductile Iron ■ Bridges ■ Traffic Plates
- Tanks, Vessels, Filters ■ Equipment

*Our state of the Art
Coatings Facility
Blasted and Coated this
Rocket Launch Stand
Prior to erection*



(714) 635-1130

Anaheim, CA 92805

A QP3 Facility